## Quickwhite Paint-on Dam

## **Material Safety Data Sheet**

We provide the information contained herein in good faith but makes no representation as to its comprehensiveness or accuracy. Individuals receiving this information must exercise their independent judgment in determining its appropriateness for a particular purpose.

We make no representations, or warranties, either expressed or implied, of merchantability, fitness for a particular purpose with respect to the information set forth herein or to the product to which the information refers. Accordingly, we will not be responsible for damages resulting from the use of or reliance upon this information.

Section 1
PRODUCT IDENTIFICATION
Quickwhite Paint-on Dam

Section II

HAZARDOUS INGREDIENTS/INDENTITY INFOR MATION Hazardous Component Osha Pei ACGIH TLV %(Optional) Aromatic Aliphatic Dimathacrylate Monomers

Section III

PHYSICAL DATA

Boiling Point: ND Specific Gravity: (H20 = 1): 1.2 Melting Point: ND

Vapor Pressure (mm Hg): ND Vapor Density (Air = 1): ND

Solubility in Water: Insoluble Evaporation Rate (Butyl acetate = 1): <1

Appearance & Odor: White gel with characteristic odor

Section IV

FIRE & EXPLOSION HAZARD DATA

Flammable Limit: ND Extinguishing Media: Dry Chemical Foam

Unusual Fire and Explosion Hazards: Material may burn if exposed to flame.

Section V

REACTIVITY DATA

Stability: Stable

Conditions to Avoid: High temperatures, visible light sources.

Section VI

HEALTH HAZARD DATA

Route(s) of entry Inhalation: No Skin: Yes Ingestion: ND

Signs or Symptoms of Exposure: Repeated contact with skin may cause irritation

and reddening.

Emergency and First Aid Procedures:

Eyes: Flush with copious amounts of water.

Skin: Wash with soap & water. Ingestion: Seek medical attention.

## Section VII

## PRECAUTIONS FOR SAFEHANDLING AND USE

Steps to be taken in case material is released or spilled: Wipe up spill and dispose of appropriately.

Waste disposal method: Dispose of in accordance with federal, state, & local regulations.

Precautions to be taken in handling & storage: Store in a cool dry area, avoid moisture sunlight or other visible light sources.

Section VIII CONTROL MEASURES

Respiratory Protection (Specify): None Protective Gloves: Recommended Eye Protection: Recommended